Westford Fire Dept. Headquarters



Westford Fire Dept. - Agenda

- Review existing Fire Department Headquarters
- Review pictures of existing Fire Department Headquarters
- Review proposed needs of new Fire Department Headquarters
- Questions/Comments

- Current headquarters was built in 1975
- Built for a call department
 - No accommodations for full-time staff
 - No room for administration staff
 - Not ADA compliant
 - Building is unable to accommodate current staffing and operations

- Unable to accommodate meetings with the public and other town departments
- Unable to accommodate Fire Prevention functions
- No separate boiler or electrical rooms
- The building is in disrepair and in need of major repairs and updating
- The lobby area is 6' by 5' and not conducive to good customer service

- Current garage space is used to capacity
- No area for decontamination
- No area for Bio-Hazard storage
- Inadequate rest rooms and shower facility
- Dormitory is inadequate and in disrepair
- No Locker room area

Building too small to house daily operations

- No office space for fire officers
- No room for EMS
- No Fire Prevention office
- No room for mandatory record storage
- Station is utilized to capacity

No existing separate EMS space for:

- Supplies
- Decon
- Storage
- Record Storage

- Supplies
 - No storage for surplus linen
 - BLS equipment
 - ALS equipment
 - EMS training equipment
 - Simulator (Stored in upstairs closet)
 - Manikins (Stored at Station 3)

- Lack of Decontamination area for:
 - Personnel
 - Equipment
 - Vehicle
 - Bio-Hazard storage
 - Blood-born pathogen
 - Soiled equipment

- Insufficient Storage for:
 - Records (Medical and Fire)
 - Reports (Medical and Fire)
 - Billing
 - Lawyer requests
 - Firefighter's Gear
 - Equipment (Medical and Fire)

- Insufficient garage space for apparatus
- No existing room to complete daily chores related to firefighting
- Lack of ample space to complete small maintenance jobs
- No janitors closet for supplies
- No area for seasonal tool storage
- Hard to check equipment inside during inclement weather

Lack of Space


- Apparatus
 - Not all vehicles are inside, which will shorten the life expectancy of the vehicle driving up the cost for early replacement
- Employee safety on apparatus floor
 - Less than two feet between the vehicles and the doors, making hard to get the stretchers out of the ambulances for cleaning and maintenance
 - Makes for a safer working environment when all equipment has a spot to be stored

- Building too small to house daily operations (ie equipment checks on all apparatus and vehicles)
- Need for Fire Prevention Office for:
 - Plan Review
 - Plan Storage
 - Permit Storage
 - A private office to conduct business with the public

THE LOBBY AREA




PUBLIC BATHROOM





 This shows the dormitory area that was leaking water.



 Not ADA compliant, no elevator in the building. 2, twenty eight step stairways to the second floor administrative offices.

ROT ON WALL NEAR THE WASH AREA

THIS SHOWS ROT AND WATER DAMAGE, RISK OF MOLD DAMAGE











Leaks and drafts
 around the employee
 entrance, causing heat
 loss

 Outside wall trim is rotting off of the building




 The boiler/electrical room now stores our spring water. It also houses our Bio-Hazard storage


BLS SUPPLY CLOSET



ALS SUPPLY CLOSET



PRESENT DECON AREA IS A
GARDEN HOSE WITH HOT AND
COLD WATER RUNNING DOWN A
FLOOR DRAIN




EMS EQUIPMENT STORAGE




W-12 AND E-1



W-10 WITH DOOR OPEN



E-1 WITH DOOR OPEN







The fire prevention office is an employee built space with limited desk space and open to the day room with no doors, no privacy. Approx. 6X8



 This is our kitchen table that is used for meetings with the public. This does not promote good business practice.

Westford Fire Dept. – New Headquarters

- The needs assessment (Oct 7, 2010) states the building should be at least 25,000 Sqft.
- Building size would allow for the following requirements;
 - Administration section
 - Operations Section (including Fire Prevention office)
 - Adequate garage space for apparatus and equipment
 - Adequate living space
 - Proper decon area
 - Adequate EMS space
 - Adequate ALS space

Westford Fire Dept. – New Headquarters

- Increase efficiency
- Should be located near center of town
- Town owned land vs. buying land
- Permanent building committee recommendations
- Re-Use of current land if possible

Westford Fire Department



Proudly serving the residents of Westford for over 100 years